

This diagram shows an exploded perspective view of a mechanical assembly. The components are labeled with numbers: 12, 14, 16, 18, 20, 22, 24, 26, 30, 32, 34, 35, 40, 42, 44, 50, 52, and 54. The assembly includes a long, curved shaft (22) with a flange at one end, a central housing or bracket (20) with a mounting flange (24), and several circular discs or washers (12, 14, 16, 18, 32, 34, 35, 40, 42). A bolt or screw (26) is shown passing through the assembly. A small pin or clip (50) is shown near the flange (52) of the shaft. A larger component (54) is shown at the bottom left, possibly a motor or actuator. The exploded view illustrates the relative positions and assembly sequence of the parts.

**BEST AVAILABLE COPY**

Fig. 3




Fig. 4







Fig. 5










Fig. 9




Fig. 10




Fig. 11




Fig. 12

Fig. 13




Fig. 14

